

भारत सरकार GOVERNMENT OF INDIA
रेल मंत्रालय MINISTRY OF RAILWAYS
रेलवे बोर्ड RAILWAY BOARD

261

No.2006/ Tele/ TC/ 2

New Delhi, 02.04.2012

The Chief Signal & Telecom Engineer's,
All Indian Railways.


The Managing Director,
RilTel Corporation of India Ltd,
10th Floor, Bank of Baroda Building,
16, Parliament Street,
New Delhi-1.

Sub: Regarding Emergency Socket Box made of FRP material.
Ref: RDSO's Letter No. STT/ RE/ ESB/ 702/ Vol-II.

RDSO has advised Railways to procure the subject material from RDSO approved sources. However, it is learnt that Railways are still procuring material from non-RDSO approved sources with the result the quality of the material is not ensured thus leading to failure of services.

Zonal Railways are therefore advised to procure the subject material from RDSO approved sources only.

Kindly ensure compliance.


(राकेश रंजन),

निदेशक, दूरसंचार,

दूरभाष : 011-23388504/ 030-44613,

फैक्स : 011-23304690/ 030-44690,

ई-मेल : dtele@rb.railnet.gov.in

o/c
P. K. S. S. S.
3/4/12

